

# HARDWARE MAINTENANCE

## Black Powder Coated Hardware

Keep your hardware looking great with a few basic steps:

1. Use warm, slightly soapy water, along with a clean sponge and/or a soft bristled brush to gently clean away any dirt or foreign substances that have settled on the surface. We recommend the Dawn basic formula dish soap.
2. Rinse thoroughly with warm water to remove all the soap.
3. Dry and buff with a clean, cotton cloth.



## WHEN?

Follow the above procedure any time it looks like it needs a clean, typically 1-2 times per year.